



Model
Number
Status
Date

		8601 IC Multi-head Cultivator SPD (8601 直流多头工具翻土头爆炸图)		0640001001_SPD	
		Exploded View		VERSION	A
				SCALE	1:1
		Designed by 林水彬		WEIGHT	6
		Checked by 付慧星		IMP DEGREE	B
		Approved by			
		Effective Date : 2018-6-19			
Rev/No	Iss	Revision note			

CHEVRON

Spare part list- CTA9500

Index No.	Service Part No.	Description	QTY in machine
1	5620334004	Hexagon Socket Screw	1.0
2	3403025001	Guard	1.0
3	5630015001	Prevailing Torque Hexagon Nut	1.0
4	3128556001	Guiding Block	1.0
5	2825759002	Tube Assembly	1.0
6	2824792002	Shaft Assembly	1.0
7	5620667001	Screw with Washer	12
8	3706735001	Right Outer Blade	1.0
9	3521094001	Outside Flange Shaft	2.0
10	3129563001	Outside Hoding Ring	2.0
11	5620039002	Screw	6.0
12	3706608001	Connecting Piece	1.0
13	5670479001	Spring Pin	2.0
14	3706734001	Left Outer Blade	1.0
15	3706733001	Right Inner Blade	1.0
16	3521093001	Inside Flange Shaft	2
17	3129565001	Inside Holding Ring	2.0
18	5620019004	Hexagon Socket Screw	8.0
19	2825753002	Right Gear Case ASSY	1.0
20	2825751002	Middle Shaft ASSY	1.0
21	3552967001	Gear Shaft	1.0
22	3552521001	Bevel Gear	1.0
23	3552964001	Output Shaft	1.0
24	2824794002	Pinion Assembly	1.0

25	3552970001	Gear	1.0
26	3706613001	Gasket	1.0
27	2825754002	Left Gear Case ASSY	1.0
28	3706732001	Left Inner Blade	1.0
29	3128734001	Sleeve	1.0
30	5680028001	Hexagon Wrench	1.0
201	2825944001	Guard Assembly	1.0
202	2825763002	Connecting Tube ASSY	1.0
203	2825756002	Right Outer Blade Set	1.0
204	2825758002	Left Outer Bla de Set	1.0
205	2825757002	Right Inner Bl ade Set	1.0
206	2826284001	Gear Case ASSY	1.0
207	2825755002	Left Inner Blade Set	1.0